

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
COLO
30-LAKW.D.Y
2A-

GLENN L. MARTIN COMPANY, HAER No. CO-75-A
Titan Missile Test Facilities, Captive Test Stand D-1
Waterton Canyon Road and Colorado Highway 121
Vicinity of Lakewood
Jefferson County
Colorado

Documentation: 13 exterior photographs

Robert Lyon, Photographer, May, July, and August 1993

CO-75-A-1	CAPTIVE TEST STAND D-1 FROM THE FERROCEMENT APRON, VIEW TOWARDS SOUTHEAST
CO-75-A-2	FLAME DEFLECTOR AT RIGHT, COUNTERFORT AT CENTER, FRAGMENT OF CONCRETE CAMERA STAND IN FOREGROUND, VIEW TOWARDS SOUTHWEST
CO-75-A-3	FLAME DEFLECTOR AT CENTER, CONNECTING TUNNEL AT CENTER RIGHT, VIEW TOWARDS SOUTHWEST
CO-75-A-4	CLOSE UP OF FLAME DEFLECTOR, VIEW TOWARDS SOUTHEAST
CO-75-A-5	CLOSE UP OF FLAME DEFLECTOR, COUNTERFORT VISIBLE AT REAR, VIEW TOWARDS SOUTHEAST
CO-75-A-6	FLAME DEFLECTOR AT LEFT, COUNTERFORT AT RIGHT, VIEW TOWARDS EAST
CO-75-A-7	COUNTERFORT, CONNECTING TUNNEL VISIBLE AT FAR RIGHT, VIEW TOWARDS SOUTHEAST
CO-75-A-8	WEST FLAME DEFLECTOR FROM REINFORCED CONCRETE SLAB ROOF, FORMER DRAINAGE AREA IN THE DISTANCE, VIEW TOWARDS NORTHWEST
CO-75-A-9	FLAME DEFLECTOR FROM REINFORCED CONCRETE SLAB ROOF, VIEW TOWARDS NORTHWEST
CO-75-A-10	REINFORCED CONCRETE SLAB ROOF FROM SOUTHEASTERN EDGE, ACCESS RAMPS AT LEFT AND RIGHT, VIEW TOWARDS NORTHWEST
CO-75-A-11	REINFORCED CONCRETE SLAB ROOF, GUARD RAIL AT CENTER, VIEW TOWARDS NORTHWEST
CO-75-A-12	REINFORCED CONCRETE SLAB ROOF FROM NORTHEASTERN EDGE, VIEW TOWARDS SOUTHWEST
CO-75-A-13	REINFORCED CONCRETE SLAB ROOF FROM SOUTHWESTERN EDGE, VIEW TOWARDS NORTHEAST